FILE NOTATIONS

Entered in NID File Location Map Pinned Card Indexed	Checked by Chief Paus Approval Letter 12-4-69 Disapproval Letter
COMPLETION DATA:	
Date Well Completed	Location Inspected
OW WW TA GW OS PA	Bond released State or Fee Land
LOGS FII Driller's Log Electric Logs (No.) E J Dual I Lat BHC Scale GR Lat M CBLog CCLog Others	···· GR-N Micro

THE TE OF UTAH DIVISION OF AND GAS CONSERVATION

	5 mg	-	-
Form appro Budget Bur	oved. cau No	42-R14	25.
ASS DEHICHATIC	DN AND	M JAIME	
J-0149708			
INDIAN, ALLOT	TES OR T	BIBE NAM	-

					5. LEASE DESIGNATION AND SERIAL NO.
APPLICATIO	N FOR PERMIT	TO DRILL C	EN OR S	THE BACK	U-0149708
1a. Type of Work	· · · · · · · · · · · · · · · · · · ·	IO DRILL, D	EN, OR P	LUG BACK	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	RILL X	DEEPEN	PLI	UG BACK 🗆	7. UNIT AGREEMENT NAME
b. TYPE OF WELL	3AS []				N/A
	WELL OTHER		ZONB	MULTIPIA	8. FARM OR LEASE NAME
			•		<u> Federal - Rock Creek</u>
3. ADDRESS OF OPERATOR	orporation	•		<u> </u>	9. WELL NO.
· Suite 1	214 - 1700 Bros	duay Danuay	Collanada O		#1
4. LOCATION OF WELL (I	214 - 1700 Broa Report location clearly and	d in accordance with	any State requirement	J2U2 ats.*)	10. FIELD AND POOL, OR WILDCAT
	of the Northwe				Wildcat 11. SEC., T., R., M., OR BLK.
At proposed prod. zo:	□∘ K-/-e.Surve	ved well loca	ition upon co	ompletion of	AND SURVEY OR AREA
	AND DIRECTION FROM NEA	will be sumbi	tted. 🗸 🎖	estable	Sec. 19, T41S-R7E
				·	12. COUNTY OR PARISE 18. STATE
Approxi	mately 60 miles	from Page Ar	rizona		*ANE
LOCATION TO NEARES	T		6. NO. OF ACRES IN		DF ACRES ASSIGNED
(Also to nearest drl 18. DISTANCE FROM PROI	g. unit line, if any)	1320 ft.	2034		160
TO NEAREST WELL, IN OR APPLIED FOR, ON TH	RILLING, COMPLETED		9. PROPOSED DEPTH		RY OR CABLE TOOLS
21. BLEVATIONS (Show wh		None	4000		Rotary
	ound Level (Est	imated)	Kaiban Tas		22. APPROX. DATE WORK WILL START
23.					11-25 (road) 12-15 (Spuc
. SIZE OF HOLE	<u> </u>	PROPOSED CASING		PROGRAM	
	SIZE OF CASING	WEIGHT PER FOOT	SETTING DI	PTH	QUANTITY OF CEMENT
12 3/4 v 8 3/4	9 5/8	32#	200'		125 sks
0 3/4	7(if necessa	ry) 20#			
Double	am Hydraulic J	ll Diougust ma	and the ADY	000	
Our Proc	mosis is to dri	יוע טעטעענ pr	eventer API	900 Will be	used while drilling.
surface	casing will be	cemented from	noie to app m casing sho	eroximatery 2	level: Well will be
drilled	with Rotary too	ls using air	and air-mis	t: drilling	hole size to be
0 3/4 .	it water from	Navalo Sands	tone makes i	t impossible	to mict dwill
conversi	on to tresh wat	er jelled mu	d Will he us	ed to drill	to annyovimatoly 20001
(cop o i	the Permian Kai	Dap formation	n). A serie	s of 20' cor	ac will haven't with as a
111.202.11	DOSSIDIE. ANV	coring pread	K OT 5' Will	he nulled a	nd 7 cardan was de
rue even	it of oil satura	TION DETAME	heade naidan	Ect Tono	. · · · · · · · · · · · · · · · · · · ·
CHILLIE 1	under Bond#1607	ID ZDUU - KA'	ibab 3000' -	Cedar Mesa	3750'. This well will be
	ander bond#100/	0/1.			《海影·全新数量,《自夏 登》
					C3/6)
. ~	eed servey p	101. E Pat	Es en acala		
• •	- moraly		8 1.		1101
ADOVA STACE DESCRIBE	PROPUSED PRINCIPAM . IT IN	PATRABAY WE'TA AAAMAD A		4. Z.F	ctive sone and proposed new productive
eventer proposal is to d	or geolog girectioneri	y, givë pertinent dat	a on subsurface loca	tions and measured	ctive sone and proposed new productive and true vertical depths. Give blowout
. 0/		10			
SIGNED U.C	1 Silvent	lel	President		
A.A.Sc	noenfeld /	TITLE _	. i es idello		DATE 11-1-69
(This space for Federa	d or State office use)				
PERMIT NO.	5-075-300	06	APPROVAL DATE		
•	,		VIEW VALE	100	
APPROVED BY		TITLE			
Conditions of Approval	" IF ANY ;			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	

Instructions

and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office. General: This form is designed for submitting proposals to perform certain well operations, as indicated, on all types of lands and leases for appropriate action by either

Item 1: If the proposal is to redrill to the same reservoir at a different subsurface location or to a new reservoir, use this form with appropriate notations. Consult applicable State or Federal regulations concerning subsequent work proposals or reports on the well. Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local

Item 14: Needed only when location of well cannot readily be found by road from the land or lease description. A plat, or plats, separate or on this reverse side, showing the roads to, and the surveyed location of, the well, and any other required information, should be furnished when required by Federal or State agency offices. State or Federal office for specific instructions.

Items 15 and 18: If well is to be, or has been directionally drilled, give distances for subsurface location of hole in any present or objective production zone.

Item 22: Consult applicable Federal or State regulations, or appropriate officials, concerning approval of the proposal before operations are started.

	40.00	1.35				
en de la companya de La companya de la co	DEC & la			1 7.3 j.	11.	74 343
699	3 /		no Marie		##**. * .	A SANT Diff e A
	· · · · · · · · · · · · · · · · · · ·			****	16937 ₀ 5	an in anning in
ji (* ptwie galiena - i	 เปลียดีหลาด สีมีเพรือวิ 	anstracos di	ស៊ីមាស់ ស្គមស៊ី (និង 	ollare t Mrs	ঞ্ধ নিক্ষা ।	n Colland La Ar Processad LA
•					ear Jeri	er job, M
	AND OF LAWS	etak e îre	Pilosoppia de	ration to	ia nan in ki	. S. S. A.
	and the state of t			٠	Longo Bass	
			2.0		TO SERVICE STATES OF THE SERVICE STATES OF T	TING SER
v ^a e	16.70 011		e e e e e e e e e e e e e e e e e e e		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	perceia Mi
			Total Pro-	en e	er er græger i til	ilireit võida 183.
	*	and the second s				
, to the question to the	Roman Communication	(4. CR. 1796) +1966	a			
, 191 4 9 345 1.63	and the second	77349 147	(148 Et 1)	16 × 77,28 8	lafter)	Ne 2332
		•				
0						
	•					
•						
			•			
•			•			
	•	•			•	
ារ ១០១ ខ្លាំ ១១ ១៤៤ ៦ ១៤ខ្លែកកែ ភព ១ ខ្លែក ខេត្ត ខ្លែកសារ ១១៤៤១ ភព ១ ខ្លែក	dres sa stok tambi	irat asig ali	nanchemile an	igadi ya Hir	the of the c	nser avear sear geografic cases geografischer
a company of the second	a w					3.2
			entransia di Santa da Santa d			
	insing mount of the second		(ear or fir	aw ia imuada Kitat‱ to∎	e for Pedera	un a. Ings rid ^{ner}
	Micha i					, এই ক্লিয়ায়ায়
	SITIT				````r	ক এই সভাববাৰ
The second secon	The state of the s	general to the second of the second of the second	4	1771.85 a	OF APPL OF A	etik trazeo

December 4, 1969

Romex Corporation Suite 1214 - 1700 Broadway Denver, Colorado 80202

> Re: Well No. Rock Creek Federal #1 Sec. 19, T. 41 S, R. 7 E, Kane County, Utah

Gentlemen:

Insofar as this office is concerned, approval to drill the above mentioned well is hereby granted. However, this approval is conditional upon the following:

- 1. A surveyor's plat is furnished this office, (Rule 8-4 (a))
- 2. A letter from your company stating that this location is unorthodox due to either geology or topography. Also, that you own all the acreage within a 660' radius of the proposed site.

The above approval is granted in accordance with Rule C-3(c).

Should you determine that it will be necessary to plug and abandon this well, you are hereby gequested to immediately notify the following:

PAUL W. BURCHELL - Chief Petroleum Engineer HOME: 277-2890 OFFICE: 328-5771

This approval terminates within 90 days if the well has not been spudded-in within said period.

Romex Corporation December 4, 1969 Page 2

Enclosed please find Form OGC-8-X, which is to be completed whether or not water sands (aquifers) are encountered desing drilling. Your co-operation with respect to completing this form will be greatly appreciated.

The API number assigned to this well is 43-025-30006 (See Bulletin D-12 published by the American Petroleum Institute).

Very truly yours,

DIVISION OF OIL 8 GAS CONSERVATION

CLEON B. FEIGHT DIRECTOR

CBF:sd Enclosures

cc: U.S. Geblogical Survey 8416 Federal Building Salt Lake City, Utah 84116 OFFICERS
PRESIDENT
A. A. SCHOENFELD
VICE PRESIDENTS
W. E. GREENMAN
EDWARD G. KADANE
J. D. KENNEDY

SECRETARY-TREASURER GRANT I. GAETH

ROMEX CORPORATION

1700 BROADWAY
SUITE 1214
DENVER, COLORADO 80202
AREA CODE 303 255-0265

DIRECTORS
C. J. DAVIDSON
JACK Q. FRIZZELL
IRIS GOLDSTON
CLAUD B. HAMILL
JOE A. HUMPHREY
WILLIAM S. KILROY
J. C. MAXWELL

January 15, 1970

State of Utah Division of Oil & Gas Conservation 1588 West North Temple Salt Lake City, Utah 84116

re: Well No. Federal Rock Creek #1

Kane County, Utah

Gentlemen:

Enclosed is the survey plat on the #1 Rock Creek Federal located 972.91' FWL and 1049.69' FNL, Sec. 19, T.41S., R.7E.

We are requesting your approval of the unorthodox location due to inaccessible terrain in the vicinity of the orthodox 40 acre spot.

The above location meets the State requirements in that the location is at least 660' from the boundries of the Romex lease covering all of the N_2 of Section 19.


Sincerely,

Grant I. Gaeth

GIG/j

Enc.

SEMMNIN



T.415, R.TE. OF THE S.L. MERIDIAN

WELL LOCATION

ROMEX NO. 1. ROCK CREEK FED. PLAT WAS PLUTTED FROM THE

ROMEX CORPORATION

DENVER, COLORADO SITUATED IN NE MANEM SEC.19

T.41S., R.TE. S.L. B.M.

KANE COUNTY, UTAH

SCALE- 1 INCH = 1000 FEET

REF. POINT 100.0FEET NORTH-

REF. POINT 210.0 FEET EAST ELEV. 422825 ELEVATIONS ARE APPROXIMATE

THIS IS TO CERTIFY THAT THE
"WELL LOCATION" SHOWN ON THIS
PLAT WAS PLOTTED FROM FIELD
NOTES OF ACTUAL SURVEY MADE
BY ME OR UNDER MY SUPERVISION
AND THAT THE SAME ARE TRUE AND
CORRECT TO THE BEST OF MY
KNOWLEDGE AND BELIEF.
DATE BURVEYED-DEC.18,1969

JEAN COLE REGISTERED LAND SURVEYOR GLENWOOD SPRINGS, COLO. CERTIFICATE NO. 1589

Kane County Wildcat Gamble

Rugged Terrain Spurs Oil Search

By Daniel K. Cunningham Tribune Business Writer

ROCK CREEK, Kane Coun--A remote, cliff-encircled nyon is the scene of a \$200 -

600 gamble by i imen.

And it shows, more than anything else, why oil exploration men are c a lled wildcatters.

The canyon is the site of Creek Cunningham Rocky Federal No. 1, a wildcat to be drilled later this month with Willard Pease Drilling Co. of Grand Junction, Colo., as con-

tractor.
"I've looked for oil for 16 years in this part of the world and I've never seen anything to rival this well," says Grant 1. Gaeth.

Mr. Gaeth, a geologist from Romex Corp., Denver, is the son most responsible for Rock Creek Federal No. 1.

F He first saw the canyon 10 in a helicaster. Since

then the canyon has been extensively photographed from the air. And Mr. Gaeth photographed led a geological team in the area two years ago.

"We spent 21 days mapping the area by boat — camping out the whole time," recalls Mr. Gaeth.

Looks Promising

The geological structure looks like a natural for holding trapped pools of oil, But no one will know for sure until a well probes the secrets hidden underground.

Why is the risk being taken?

"Because of the size of the structure and the amount of oil that could be there - if it's productive," says Mr. Gaeth.

Romex is the operator for the joint venture, which includes participation by Mountain Fuel Supply Co., Occidental. Petroleum, Crest sources and Skyline Oil Co. Romex itself is a closed corporation bankrolled by about 10 Texas oil independents.

About two years were spent putting together the

30,000-acre package which controls the structure.

THE REAL PROPERTY OF THE PARTY OF THE PARTY

"I talked them into it on the basis of the large, untested structure and the relatively low acreage costs," says Mr. Gaeth.

He calls the site "the most inaccessible country in the contiguous states.

"It costs more to drill a foot of hole in this country than any place else in the United

States, except Alaska."

For comparison, he noted Rock Creek Federal will be drilled to about 3,800 feet at a cost of \$200,000.

"To give you some idea of the inaccessibility, you can drill a 4,000 foot well in the Julesburg Basin 100 miles from Denver for just \$25,000,"

Boat Trip

When Mr. Gaeth staked the location, traversing theusand-eled 45 miles by boot from Wahweap Marina, up Lake Powell, to Rock Creek Bay, then walked five miles to the location, traversing thousandfoot-high cliffs which ring the entire area.

But it would be impossible to get a drilling rig into the site by boat. It would have to be hauled over 60 miles of graded and ungraded road wending northwest of Glen Canyon City.

The last portion of the trail was an almost useless Bureau of Reclamation road with 30 percent grades in places.

"The last time I went along the road we used Honda trail bikes and it took two men to push one bike up some of the prades."

C & W Construction Co, coab, was hired for \$50,000 to approve the road, which itself an epic story.

It was thought too en wive to maintain a camp the 30 miles of construction work, so crews weeks fown to their jobs each marking to their jobs each night. The trip took 1

The pilot was J. D. Wilson, owner of the construction

him.
"To do the job, he develthe road.

Edge End

"One of the strips is a real bearcat, it ends on the edge of a cliff 1,500 feet above the canyon floor.

"I saw Wilson take off a couple of times. He literally dropped out of sight because he goes off the rim of the canyon when he takes off.

"Wilson had done an a anding job, consideration money he had to spend,"

Mr. Gaeth.
"And the road now will be

there for use by other.


However, it's still a fourmour drive from Gled Campon City to the well, so the five tien who will operate the drilling rig will be sown in daily.

The wildcat will test to the Cedar Mesa formation. Main objective is the Kaibab formation, which produced 35 miles northwest at the Upper Valley Field. If the oil is there in sufficient quantity an additional \$250,000 will be spent to build a road which will allow crude to be trucked out for refining.

It's taken two months to construct the road into the well site. The drilling rig leaves this week and will require 30 days for its trip from Grand Junction, including 12 days along the rebuilt road.

But when the rig is in, it will take just 15 days to drill the hole."

"As Mr. Gaeth says, 🤻 t's a real dizzy.'



ROMEX CORPORATION

OFFICERS PRESIDENT A. A. SCHOENFELD VICE PRESIDENTS JACK H. MAYFIELD EDWARD G. KADANE J. D. KENNEDY SECRETARY-TREASURER GRANT I. GAETH

1776 LINCOLN SUITE 420 DENVER, COLORADO 80203 AREA CODE 303 255-0265

DIRECTORS C. J. DAVIDSON JACK Q. FRIZZELL IRIS GOLDSTON CLAUD B. HAMILL JOE A. HUMPHREY WILLIAM S. KILROY J. C. MAXWELL

March 23, 1970

Drilling Participants

Re: Romex Federal-Rock Creek No. 1 1049.69' FNL & 972.91' FWL Section 19, T-41-S, R-7-EKane County, Utah

Elevation 4157 Derrick Floor

Gentlemen:

The following outline is a summary of the drilling history, formation tops, logging evaluation and testing of the captioned well:

- The Rock Creek #1 spudded Thursday afternoon, January 29, 1970 and drilled to a total depth of 3969' on February 27, 1970. The following USGS approved plugging instructions were concluded 12:30 A.M. March 1, 1970:
 - Α. 30 sks at 3784-3704'
 - 30 sks at 3040-2960' 30 sks at 2575-2495' В.

 - 35 sks at base of 9 5/8" casing set at 236-146'
 - 5 sks at top of casing below dry hole monument threaded to 9 5/8" surface casing.
- After setting 247' of 9 5/8", 8 round, 32 lb. surface casing 236' below the ground with 125 sks regular cement and 2% CACL, an 8 3/4" hole was mist-drilled to 2045' in the Triassic Chinle formation. One pit of mud was used to heal the Navajo porosity and the hole was mud drilled to total depth without any significant lost circulation zones.
- A Monitor mud logging unit was installed and commenced logging below 250' on February 3, 1970. Gas shows of 40 and 60 units were recorded at 3050' and 3188' in Kaibab and White Rim formations respectively. The first show was cored in the interval 3050' to 3083' recovering approximately 10 to 12' of Dolomite with a heavy tarry residual oil filling secondary porosity. The White Rim gas show yielded 1550' of muddy water on DST.

4. The following sample and electric tops below a derrick floor elevation of 4157' are:

FORMATION	SAMPLE TOP	E. LOG TOP	SEA LEVEL DATUM
JURASSIC Navajo	50		+4107
TRIASSIC Keyenta Wingate Chinle Shinarump Moenkopi	1945 2560 2752	1362 1691 1940 2585 2781	+2795 +2466 +2217 +1572 +1376
PERMIAN Kaibab White Rim Organ Rock Cedar Mesa	3032 3180 3388 3802	3049 3177 3386 3801	+1108 + 980 + 771 + 356

5. Two cores were cut in the Permian Kaibab formation:

A. Core #1

Interval 3050-3053 Recovered 3' of dolomite, light tan micro crystalline, siliceous with chert and trace glauconite after skeletal molds, very faint oil stain and cut flouresence, no visible porosity.

B. Core #2

Interval 3053-3083

Recovered 30' consisting of 2' light tan and very siliceous dolomite as above. 6' dolomite, tan, fine to very fine crystalline. trace brown oil stained anhydrite filled skeletal molds. Fair intercrystalline vugular porosity, fair yellow-brown cut and cut flouresence, 7' dolomite buff grey to light tan, skeletal with pelecypod, gastropod and shell fragment molds. Numerous zones of heavy black tarry oil filling inter-crystalline and vugular porosity. Excellent cut flourescense, trace anhydrite filling of skeletal molds as above.

dolomite light tan very fine to finely crystalline with 10 to 25% - very fine to angular quartz grains. Abundant anhydrite filling of fossil molds. Trace light brown oil stain with pale yellow cut flouresence, poor to fair intercrystalline porosity. No show of oil in lower 2'. 5' dolomite buff grey and light tan interbedded in 1' to 2' intervals as above. Trace inter-crystalline porosity, stylolitic at 3078. 3' dolomite light tan, very fine to fine crystalline with 10 to 20% very fine to fine angular quartz grains. Abundant skeletal molds, poor to fair intercrystalline and vugular porosity. Fossil molds partially filled with anhydrite. Last 1' contained excellent porosity that bled fresh water.

- 6. Had two fishing jobs at 3210' and 3472'. First fish recovered with overshot in 5 hours. Second fish recovered with wash over pipe in 86 hours. 20 additional hours of rig time used to complete tubascoping drill pipe and drill collars. Discarded 51 of 106 joints of 3½ drill string and 7 of 12 drill collars. Contractor was unable to furnish sufficient weight to afford maximum penetration while making the bottom 500' of hole.
- 7. Electric log formation evaluation consisted of a complete suite of logs necessary for a synergetic log systems analysis. A copy of this log systems analysis will be furnished to the drilling participants in the very near future. The following are porosities and water saturations over specific intervals analyzed in the field:
 - A. Interval 2700-2708 Sandstone RW = .7, Rt = 29, porosity = 15% SW = 100%
 - B. Interval 3058-3060 Dolomite RW = 1.5, Rt = 100, porosity = 21% SW = 55%
 - C. Interval 3111-3118 Dolomitic Sandstone

 RW = 1, Rt = 100, porosity = 10%

 SW = 83%

- D. Interval 3202-3208 Sandstone RW 1, Rt = 80, porosity = 13% SW = 80%
- E. Interval 3809-3812 Sandstone RW = .28, Rt = 38, porosity = 10% SW = 97%
- F. Interval 3862-3881 Sandstone RW = .28, Rt = 37, porosity = 8% SW = 100%
- 8. Two DST's were run in the interval 3180-3225:
 - A. DST #1 was a mis-run. The Hook wall packer seat failed as the tool was opened.
 - B. DST #2 in the interval 3180-3225' in the Permian White Rim Sandstone. Test recovered 1550' of muddy fresh water. The RW = 2.72 at 67 Farenheit, with 900 ppm chloride. The IFP = 2.42-320 #'s in 15 minutes; ISP = 1473 #'s in 60 minutes; FFP = 288-754 #'s in 180 minutes; FSIP = 1470 #'s in 180 minutes; HP = 1821-1787# Assuming the maximum calculated shut in pressure of 1470 lbs. per sq. in. and a conversion of 2.31 lbs. per foot the potentiametric surface of the White Rim reservoir would be 4372' indicating a strong potentiametric drop towards the axis of the Kaiparowits basin to the southwest.
- 9. Structurally, the Kaibab formation was topped within 50' of our projected depth and was 867' high to the Cleary Fund-Romex Utah State #1-16 in Section 16, T-40-S, R-5-E and 617' low to the Shell Soda Unit #1 approximately 10 miles to the northeast in Section 2, T-40-S, R-7-E. There are no direct structural comparisons on the Rock Creek anticline; however, if the lowest possible dip of 1° were projected from the Shell-Soda well, the top of the Kaibab would have been at least 900' structurally low in the Rock Creek well.
- 10. Stratigraphically, the Kaibab reservoir had in excess of 35' of dolomite porosity averaging from 12 to 22%. This reservoir contained a heavy black tarry residual oil in the top 12'. Both the White Rim and Cedar Mesa sandstone reservoirs were disappointing with top porosities of 13% and 8% respectively. In both these reservoirs primary porosity had been plugged with secondary anhydrite cement.

Copies of the Monitor mud log and Halliburton DST report are being forwarded with this letter. Please let us know if you have not already received copies of the logs and the core analysis.

Very, truly yours,

Grant I. Gaeth

GIG: jpf Enclosures

	E STÁTE O OF OIL AN	F J J CONSERVATION	SUBMIT IN TRIPLE (Other instructions of the	Form approved. Budget Bureau No. 5. LEASE DESIGNATION AND SI	
			verse side)	U-0149708	ERIAL NO.
CUNID	DV NOTI	TEC AND DEDODIC ON	AL AMELLO	6. IF INDIAN, ALLOTTEE OR TI	RIBE NAME
		CES AND REPORTS OF the design of the deepen or plug back			
	se "APPLICAT	is to drill or to deepen or plug back TION FOR PERMIT—" for such prop	osals.)	N/A 7. UNIT AGREEMENT NAME	
1. OIL N GAS T				N/A	
WELL LA WELL L. 2. NAME OF OPERATOR	OTHER			8. FARM OR LEASE NAME	
R	omex Corp	oration		Federal - Rock Cr	reek
3. ADDRESS OF OPERATOR				9. WELL NO.	
S (Par	uite 420	- 1776 Lincoln Denve arly and in accordance with any St	er, Colo. 80203	# 1 10. FIELD AND POOL, OR WILD	OCATE
See also space 17 below. At surface)	arry and in accordance with any or	are requirements.	Wildcat	
	FNL & 97	'2.91' FWL		11. SEC., T., R., M., OR BLK. AN SURVEY OR AREA	1D
	• • •			SURVEI OR AREA	
				Sec. 19 T41S-R7E	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RI	r, GR, etc.)		
		4157 DF	· · · · · · · · · · · · · · · · · · ·		<u>Utah</u>
16.	Check App	propriate Box To Indicate Nat	ture of Notice, Report, or C	Other Data	
NOT	CICE OF INTENT	ION TO:	SUBSEQ	UENT REPORT OF:	
TEST WATER SHUT-OFF	PU	ULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT	M	ULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE		BANDON*	(Other)	ABANDON MENT*	
REPAIR WELL (Other)	C	HANGE PLANS	(Note: Report results	of multiple completion on We letion Report and Log form.)	ell .
nent to this work.) *		ATIONS (Clearly state all pertinent of ally drilled, give subsurface location	·		tarting any zones perti-
, , , , , , , , , , , ,			· 2000 / 10,10 / 10,10 · 1,9		a 13
		sks at 3784-3704'			
		sks at 3040-2960'			• * *
		sks at 2575-2495' sks at base of 9 5/8'	" casing set at 236.	-146'	
		sks at top of casing I			
		to 9 5/8" surface cas			
				•	
Enc	losures:	<pre>2 copies completion 2 core analysis</pre>	report, 1 set E log	s, 2 mud logs &	
					e e
				*	
				e	
18. I hereby certify that the	e foregoing is	true and correct			4.5
SIGNED JUNE	ZYCY CA	TITLE Secre	etary-Treasurer	DATE 4/6/70	
(This space for Federal	or State office	e use)			
APPROVED BY		TITLE		DATE	
CONDITIONS OF APP	ROVAL, IF AN				

CA 20

CORE LABORATORIES. INC.

Petroleum Reservoir Engineering DALLAS, TEXAS

Page	No	1

CORE ANALYSIS RESULTS

Comp	nny Romex Co			F						File	RP-3-2L	107
W ell	l Federa	1 1- Rock	Creek	C	ore Ty	pc Dia. C	onv.	4"	1 ,	Date	e Report_2-16-	70
Field	Wildcat_			D	rilling	Fluid		. <u></u>		_ Ana	lysts Mohl	-
Coun	ty Kane	State U	tah	Elev.		_Location	NW NW	Sec	19 -		•	
	,				•						• • • • • • • • • • • • • • • • • • • •	
SANCE	್ ಗಾರೀರ⊭ಗಳ್ಳಾರರ	SL ANHYDRITE		DATILL SANDY SO	-	al Abbreviat	CRYSTALLIF		8ROWN		PRACTURED PRAC	3L1GHTL7.8L/
MILALIT LIMP L	TH CHEST CH	CONGLOME	RATE CONG	SHALY BHY		MEDIUM MED	GRAIN GRN		GPAY 6	1 *	LAMINATION LAM	VERY . V/
, , ,					RESIDU	AL SATURATION	1		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
STIMBER STIMBER	DEPTH	PERMEA	ARCYS	POROSITY		CENT PORE	1				DESCRIPTION REMARKS	
PATE NAME OF PA	F.F.E.T	Max。	900	PER CENT (CIL	WATER	1					
1	305 0-51	0.08*		2.4	0.0	88.6	Dolo,	gry,	syc,	shly		
2	3051-52	<0.1	<0.1	2.4	0.0	86.6	Dolo,	gry,	suc			
3	3052-53	0.8	0.3	2.7	0.0	95.3	Dolo,	gry,	suc			
ls.	3053-54	3 .3	0.9	4.5	0.0	81.9	Dolo,	gry,	SUC			
15	3054-55	0.9	0.4	3.4	0.0	87.6	Dolo,	gry,	suc			
6	3055-56	21.	12.	15.6	0.5	83.1	Dolo,					•
7	3056-57	11.	3.1	13.9	2.2	71.8	Dolo,					
8	3057-58	27.	27.	18.1	2.3	80.4	Dolo,					
9	3058-59	58.	30.	16.9	4.7	7 5•5	Dolo,					
10	3059-60	0.6	0.6	19.7	2.6	80.6	Dolo,					
11	3060-61	23.	21.	21.6	3.0	82.1	Dolo,			Agy		•
12	3061-62	28.	21.	19.5	5.8	76.8	Dolo,					
13	3062-63	15.	13.	16.2	5.2	76.1	Dolo,					
14	3063-64	7.0	7.0	16.8	9.1	68.1	Dolo,				•	
15	3064-65	0.9	0.8	11.4	2.7	74.4	Dolo,					4.5
16	3065-66	3.1	3.1	16.1	4.2	75.8	Dolo,			ngy	•	. 7
17	3066-67	4.1	3.5	16.7	1.9	79.1	Dolo,					
18	3067-68	0.5	0.1	10.1	8.3	62.2	Dolo,					
19	3068-69	3.8	3.2	13.0	1.5	75.4	Dolo,					
20	3069-70	0.8	0.8	12.7	0.0	77.5	Dolo,					
21	3070-71	2.2	1.7	5.8	0.0	62.2	Dolo,					
22 23	3071 -7 2	4.4 1.8	2.6	17.1	0.0	78.1	Dolo,	gry,	suc,	vgy		1.
21	3072 -7 3 3073 - 74	0.2	0.1	14.9 9.8	0.0	78.8	Dolo,					
25 25	3074 -7 5	2.0	1.8	14.7	0.0	73.8 76.6	Dolo,					
26	3075-76	0.1	<0.1	6.5	0.0	69.9	Dolo,	gry,	suc	AgA.		
27	3076-77	0.2		12.0	0.8	76.5	Dolo,			90 0000		
28	3077-78	0.2	0.1	10.8	0.6	74.9	Dolo,	gry,	Suc,	ARA		
59	3078 -7 9	√0.1	<0.1	8.2	0.0	76.1	Dolo,	gry	Suc			
30	3079 - 80	₹0.1	0.1	10.3	0.8	78.1	Dolo,					
31 31	3080-81	Ø.1	0.1	8.6	0.0	68.7	Dolo,					
32	3081-82	0.5	0.3	10.6	0.0	78.8	Dolo,	Br J +	ann			
3 3	3082-83	0.5	0.4	11.9	0.0		Dolo,			Vov		
در	JUU E-0 J	5. 7	U•4	*** • 7	9.0	. 1740	moro,	Ry y	وبالمات	* 6 J		

* Denotes plug permeability

These analyses, opinions or interpretations are based on observations and materials supplied by the client to whom, and for whose exclusive and confidential use, this report is made. The interpretations or opinions expressed represent the best judgment of Circ Laboratories, line, fall errors and omissions excepted); but Core Laboratories, Inc. and its officers and employees, assume no responsibility and make no warranty or representations, so the productivity, proper operations, or profitableness of any oil, gas or other mineral well or sand in connection with which such report is used or relied upon.

April 10, 1970

Romex Corporation 1776 Lincoln Street Suite 420 Denver, Colorado 80203

> Re: WELL No. Rock Creek Federal #1 Sec. 19, T. 41 S, R. 7 E, Kane County, Utah

Gentlemen:

We are in receipt of your logs for the above mentioned well which have been marked "tight hole". Please refer to Rule C-5(b), General Rules and Regulations and Rules of Practice and Procedure.

In order to hole this information confidential we must have a letter from your company requesting that this data be withheld from open file. If we do not hear from you by April 24, 1970, we will assume that the information may be released.

Very truly yours,
DIVISION OF OIL & GAS CONSERVATION

SCHEREE DEROSE SUPERVISING STENOGRAPHER